



Material Safety Data Sheet [OSHA 29 CFR 1910.1200]

The QUIKRETE® Companies
One Securities Centre
3490 Piedmont Road, Suite 1300
Atlanta, GA 30329

Emergency Telephone Number
(770) 216-9580

Information Telephone Number
(770) 216-9580

Revision: October 2005

MSDS L2

SECTION I: PRODUCT IDENTIFICATION

<u>QUIKRETE® Product Name</u>	<u>Code #</u>	<u>QUIKRETE® Product Name</u>	<u>Code #</u>
CEMENT COLOR (LIQUID)	1317	LIQUID STUCCO COLORS	1323
MORTAR AND STUCCO COLOR	1319	LIQUID STUCCO COLOR CONCENTRATE	5839

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

Hazardous Components	CAS No.	PEL (OSHA) mg/M ³	TLV (ACGIH) mg/M ³
Iron Oxide Pigments (1)	01309-37-1	5	5
(1) Exposure limit as a nuisance dust. A dust hazard is not expected during normal usage of this product.			

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

Appearance:	Liquid
Color:	Buff, Tan, Yellow, Brown, Black, Red
Odor:	None
Melt Point/Freeze Point:	28°F
Boiling Point:	160-200°F
Vapor Pressure:	Not Known
Specific Gravity:	1.7-1.9
Bulk Density:	14-16 lb./gallon
Solubility in Water:	Very slightly
% Volatile by Volume:	Not Known

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

Flash Point F(C):	Not applicable
Flammable Limits:	
LEL:	Not applicable
UEL:	Not applicable
Extinguishing Media:	Not flammable
Special Fire Fighting Procedures:	None
Unusual Fire & Explosive Hazards:	None



SECTION V - REACTIVITY DATA

Stability:	Stable
Incompatibility:	None
Hazardous Decomposition or By-Products:	None
Hazardous Polymerization:	Will not occur

SECTION VI - HEALTH HAZARD DATA

Primary Route(s) of Exposure:	Eye and skin contact, inhalation, ingestion
Human Effects & Symptoms of Overexposure:	
Acute:	None Known
Chronic:	None Known
Medical Conditions Aggravated by Exposure:	None Known
Carcinogenicity:	None Known
Emergency & First Aid Procedures:	
Eye Contact:	Flush eyes with plenty of water, lifting lids periodically for at least 15 minutes. Consult a physician if irritation persists.
Skin Contact:	Wash with soap and water
Inhalation:	Remove from dusty area to fresh air. If not breathing give artificial respiration. If breathing is difficult, give oxygen. Call a physician.
Ingestion:	Immediately contact a physician.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be Taken in Case Material is Released or Spilled: Common housekeeping, vacuum or scoop material into a container for reclamation or disposal.

Waste Disposal Method: Material which cannot be reclaimed should be dried and land filled in accordance with local, state and federal regulations.

Precautions to be Taken in Handling and Storage: Store above freezing. Material should be kept in an airtight water-proof container. Avoid contact with eyes and skin. Wash thoroughly after handling.

Other Precautions: Keep containers sealed to keep the product from drying out.

VIII - CONTROL MEASURES

Respiratory Protection:	Not required
Ventilation:	Not required
Protective Gloves:	Rubber gloves
Protective Glasses:	Safety glasses or goggles
Work/Hygiene Practices:	Wash thoroughly after handling and before eating.

NOTE: The information and recommendations contained herein are based upon data believed to be correct. However, no guarantee or warranty of any kind, express or implied, is made with respect to the information contained herein. We accept no responsibility and disclaim all liability for any harmful effects which may be caused by exposure to silica contained in our products.